

CASE HISTORY HONDA CIVIC

Below is a picture of the main engine management E.C.U on a Honda civic as it was presented to us to fit an Apexi v-Tec controller. From the picture it can be seen that previous wiring attempts to install the unit were aborted and a very poor standard of rejoining the wiring loom had been made using chocolate blocks and twisted wires.



After repairing the wiring by soldering and insulating with heat shrink we were able to install the controller and be sure of a quality job with long term reliability.



